## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

: 7,132,613 B2

APPLICATION NO.: 10/828602

DATED

: November 7, 2006

INVENTOR(S)

: Smith et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

## Column 8,

Lines 43-44 should read -- respective load coil from the transmission line to selectively connect the load coil to the transmission line. --

Signed and Sealed this

Page 1 of 1

Twenty-seventh Day of February, 2007



JON W. DUDAS
Director of the United States Patent and Trademark Office